MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Other Options

Return to menu
Plot this site in State Library Digital Atlas
Plot this site in Google Maps
View scanned well log (7/21/2009 1:24:19 PM)

Site Name: LETANG ROBERT AND WANDA
GWIC Id: 201037

Section 1: Well Owner(s)

1) LETANG, ROBERT AND WANDA (MAIL)
1869 LABRANT ROAD
RUDYARD MT 59540 [06/05/2001]

Section 2: Location

Township	Range	Section	Quarter Sections
27N	19W	5	

County	Geocode	Parcel
FLATHEAD		

Latitude	Longitude	Geomethod	Datum
48.132176	-114.041561	TRS-SEC	NAD83

Ground Surface Altitude	Ground Surface Method	Datum	Date

Addition	Block	Lot
ECHO LK SUMMER HOMES		23

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: CABLE
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Tuesday, June 5, 2001

Section 6: Well Construction Details

Borehole dimensions

From	To	Diameter
0	56	6

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-1.5	51	6	0.250			STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
51	56	6			OPEN HOLE

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	0	CONT FED BENTONITE	

Section 7: Well Test Data

Total Depth: 51
Static Water Level: 40
Water Temperature:

Bailer Test *

20 gpm with _ feet of drawdown after 1 hours.
Time of recovery 1 hours.
Recovery water level 40 feet.
Pumping water level 42 feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

Section 9: Well Log

Geologic Source

Unassigned

From	To	Description
0	8	COBBLES SANDY SOIL
8	22	CLAY COBBLES GRAVEL
22	39	CLAY SILT WATER SEAPS
39	53	GRAVEL SAND WATER
53	56	SILTY SAND WATER SEAPS

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name:
Company: WELL DONE DRILLING & PUMP CO
License No: WWC-576
Date Completed: 6/5/2001